



Product/Process
Change
Notification
PCN08139

Product:	Clincher™ Latch Header Connectors	Part Numbers Concerned:	See list attached
Product Manager:	Alejandro Aguirre	Issue Date:	Oct 3 08
		Page(s):	1/1
Distribution:	GLOBAL		

Subject:

Clincher™ Latch Header Connectors color change only

Nature of Change:

Housing color for all Clincher™ Latch Header Connectors will be change from “black” to “natural” color.

Impact of change:

None. Resin will remain the same. Only the color will change. These connectors are internal board-to-cable connectors and color is not a customer requirement. Older black color and new natural color Clincher™ latch header connectors will mate to Clincher™ receptacle connectors designed for termination to flat flexible cable (FFC).

Reason for chance:

This change will consolidate resins and support increased responsiveness to customers.

Implementation Date:

After January 9th , 2009

Affected Part Numbers:

See attached file.

Action Required:

Notify all customers for this color change.

For questions regarding this PCN contact:

Alejandro Aguirre

Product Manager

Email.- alejandro.aguirre@fci.com

MX Phone 01152 (656) 692-5872

USA Phone (915) 356-1172

MX Mobile Phone (656) 130-3351

Or contact your nearest FCI representative