
Smart Sensors

OMRON

ZX Series



The Continuing Evolution of Smart Sensors

Presenting a New Laser-type ZX-LDA□-N Amplifier Unit









a Smart Sensor!!

OMRON Offers Sensor Users New Choices

What's Style?

Top Priority Placed on Easy Operation

Advanced functions and performance plus easy op This is a major feature of the ZX Series. Experience operation that doesn't get any easier.



A Full Complement of Practical Functions

By simply fitting a Calculating Unit between two Amplifiers, the processing results of two Sensors can be displayed on a single Amplifier. Setting parameters need to be input only on one Amplifier.













Advanced to Small Studies

Advanced Functions Respond to Evolving Needs

More User Friendly New Function


Zero Reset Time Display

A reference value other than zero can be set as the zero reset



Linear Output Correction

Various factors, such as conversion errors occurring with connected devices, may cause the output value displayed on the Amplifier to differ from the actual output from a voltmeter. Adjusting the Amplifier display while monitoring the actual output on a voltmeter can eliminate the difference between the two values




Present Value Display

The sub-digital display shows present values when the hold function is enabled. This makes it easy to check whether a measurement is within range.



Automatic Teaching


Maximum and minimum measurement values can be set as thresholds when automatic teaching is executed. It is useful for setting threshold values from actual measurements while the workpiece is moving.








Enhanced Hold Function New Function



Delay Hold/Average Hold

The delay hold function measures only signals within the desired sampling time after a specified time delay from the trigger. The newly added average hold function is especially useful for measuring large workpieces with uneven surfaces.






Previous Value Comparison Function


Gradual changes in measurements due to machine temperature changes or other factors can be ignored in certain situations, such as when detecting foreign matter around bearings. The previous value comparison function effectively detects any changes between previous and

present values.



Multiple-point Measurements Computed Using 1 Point

The result computed for one point can be used as a basis for the output for every other point. This is especially useful for multiple-point measurements





ZX-LDA-N



Ordering Information

■ Sensors

Sensor Heads (Reflective)

Optical system	Beam shape	Sensing distance	Resolution*	Model
Diffuse reflective	Spot beam	40±10 mm	2 μm	ZX-LD40
		100±40 mm	16 μm	ZX-LD100
		300±200 mm	300 μm	ZX-LD300
	Line beam	40±10 mm	2 μm	ZX-LD40L
		100±40 mm	16 μm	ZX-LD100L
		300±200 mm	300 μm	ZX-LD300L
Regular reflective	Spot beam	30±2 mm	0.25 μm	ZX-LD30V
	Line beam			ZX-LD30VL

^{*} For an average count of 4,096.

Sensor Heads (Through-beam)

Optical system	Measuring width	Sensing distance	Resolution*	Model
Through-beam	1-mm dia.	0 to 2000 mm	4 μm	ZX-LT001
	5 mm	0 to 500 mm		ZX-LT005
	10 mm			ZX-LT010

^{*} For an average count of 64.

Amplifier Units

Appearance	Power supply	Output type	Model
rann i	DC	NPN	ZX-LDA11-N
		PNP	ZX-LDA41-N

Note: Compatible connection with the Sensor Head.

Accessories (Order Separately) Calculating Unit

Appearance	Model
	ZX-CAL2

Side-view Attachments

Appearance	Applicable Sensor Head	Model
	ZX-LT1001/ LT005	ZX-XF12
	ZX-LT010	ZX-XF22

Cables with Connectors on Both Ends (for Extension)*1

Cable length	Model	Quantity
1 m	ZX-XC1A	1
4 m	ZX-XC4A	
8 m	ZX-XC8A	
9 m *2	ZX-XC9A	

^{*1.} ZX-XC□R robot cable type also available.

Smart Monitor Sensor Setup Tool for Personal Computer Connection

Appearance	Name	Model
	ZX-series Communications Interface Unit	ZX-SF11
CD-ROM	ZX-series Communi- cations Interface Unit + ZX-series Sensor Setup Soft- ware Basic	ZX-SFW11V3 *1, *2
CD-ROM	ZX-series Sensor Setup Software	ZX-SW11EV3 *1

^{*1.} The ZX-SFW11V3 or ZX-SW11V3 is required to use Smart Monitor with the ZX-LDA11-N/41-N. Earlier versions cannot be used.

^{*2.} For use only with Reflective Sensors.

^{*2.} The ZX-SFW11EV3 SmartMonitor can be used only to set functions and monitor waveforms.

Specifications

■ Sensor Heads (Reflective)

Item Model	ZX-LD40	ZX-LD100	ZX-LD300	ZX-LD30V	ZX-LD40L	ZX-LD100L	ZX-LD300L	Z3X-LD30VL
Optical system	Diffuse reflective			Regular reflec- tive	Diffuse reflective	Diffuse reflective		Regular reflective
Light source (wave length)	Visible-light semi	conductor laser w	ith a wavelength o	f 650 nm and an	output of 1 mW max.; class 2			
Measurement point	40 mm	100 mm	300 mm	30 mm	40 mm	100 mm	300 mm	30 mm
Measurement range	±10 mm	±40 mm	±200 mm	±2 mm	±10 mm	±40 mm	±200 mm	±2 mm
Beam shape	Spot				Line			
Beam size*1	50-μm dia.	100-μm dia.	300-μm dia.	75-μm dia.	75 μm x 2 mm	150 μm x 2 mm	450 μm x 2 mm	100 μm x 1.8 mm
Resolution*2	2 μm	16 μm	300 μm	0.25 μm	2 μm	16 μm	300 μm	0.25 μm
Linearity*3	±0.2% FS (entire range)	±0.2% FS (80 to 120 mm)	±2% FS (200 to 400 mm)	±0.2% FS (entire range)	±0.2% FS (32 to 48 mm)	±0.2% FS (80 to 120 mm)	±2% FS (200 to 400 mm)	±0.2% FS (entire range)
Temperature characteristic*4	±0.03% FS/°C (E	-0.03% FS/°C (Except for ZX-LD300 and ZX-LD300L, which are ±0.1% FS/°C.)						
Ambient illumination	Incandescent lan	ncandescent lamp: 3,000 & max. (on light receiving side)						
Ambient temperature	Operating: 0 to 5	Operating: 0 to 50°C, Storage: –15 to 60°C (with no icing or condensation)						
Ambient humidity	Operating and st	operating and storage: 35% to 85% (with no condensation)						
Insulation resistance	20 M Ω min. at 50	0 MΩ min. at 500 VDC						
Dielectric strength	1,000 VAC, 50/60	.000 VAC, 50/60 Hz for 1 min						
Vibration resistance (destruction)	10 to 150 Hz, 0.7	0 to 150 Hz, 0.7-mm double amplitude 80 min each in X, Y, and Z directions						
Shock resistance (destruction)	300 m/s ² 3 times	300 m/s ² 3 times each in six directions (up/down, left/right, forward/backward)						
Degree of protection	IEC60529, IP50	IEC60529, IP50					IEC60529, IP40	
Connection method	Connector relay (standard cable length: 500 mm)							
Weight (packed state)	Approx. 150 g Approx. 250 g Approx. 150 g Approx. 250 g				Approx. 250 g			
Materials	Case: PBT (polybutylene terephthalate), Cover: Aluminum, Lens: Glass Case and cover: Aluminum, Lens: Glass Case: PBT (polybutylene terephthalate), Cover: Aluminum, Lens: Glass Case: PBT (polybutylene terephthalate), Cover: Aluminum, Lens: Glass			Aluminum, Lens:				
Accessories	Instruction sheet	Instruction sheet, Laser warning label (English)						

^{*1.} Beam size: The beam size is defined by $1/e^2$ (13.5%) of the strength of the beam at the beam center (measured value). Incorrect detection may occur if there is light leakage outside the defined spot and the material around the sensing object is more reflective than the sensing object.

Note: Highly reflective objects can result in incorrect detection by causing out-of-range measurements.

■ Sensor Heads (Through-beam)

0			
Case: Polyetherimide, Case cover: Polycarbonate, Unit cover: Glass			
0.3 N·m max.			
Optical axis adjustment seal, sensor head-amplifier connection cable (1.5 m), instruction sheet			

^{*1.} This value is obtained by converting the deviation ($\pm 3\sigma$) in the linear output that results when the sensor head is connected to the amplifier unit, into the measurement

outside the defined spot and the material around the sensing object is more reflective than the sensing object.

*2. Resolution: The resolution is the deviation (±3σ) in the linear output when connected to the ZX-LDA Amplifier Unit. (The resolution is measured with the standard reference object (white ceramic), at the measurement point with the ZX-LDA set for an average count of 4,096 per period.) The resolution is given at the repeat accuracy for a stationary workpiece, and is not an indication of the distance accuracy. The resolution may be adversely affected under strong electromagnetic fields.

*3. Linearity: The linearity is given as the error in an ideal straight line displacement output when measuring the standard reference object. The linearity and measurement values vary with the object being measured.

*4. Temperature characteristic: The temperature characteristic is measured at the measurement point with the Sensor and reference object (OMRON's standard reference object) secured with an aluminum jig.

^{*2.} For an average count of 64. The value is 5 μm for an average count of 32. This is the value that results when a minimum sensing object blocks the light near the center of the 1-mm measurement width.

^{*3.} For an average count of 64. The value is 5 μm for an average count of 32.

■ Amplifier Units

Item Model	ZX-LDA11-N	ZX-LDA41-N	
Measurement period	150 µs		
Possible average count settings*1	1, 2, 4, 8, 16, 32, 64, 128, 256, 512, 1,024, 2,048, or 4,096		
Temperature characteristic	When connected to a Reflective Sensor Head: 0.01% FS/°C, When connected to a Through-beam Sensor Head: 0.1% FS/°C		
Linear output*2	4 to 20 mA/FS, Max. load resistance: 300 Ω , \pm 4 V (\pm 5 V, 1 to 5 V *3),	Output impedance: 100 Ω	
Judgement outputs (3 outputs: HIGH/PASS/LOW)*1	NPN open-collector outputs, 30 VDC, 50 mA max. Residual voltage: 1.2 V max.	PNP open-collector outputs, 30 VDC, 50 mA max. Residual voltage: 2 V max.	
Laser OFF input, zero reset input, timing input, reset input	ON: Short-circuited with 0-V terminal or 1.5 V or less OFF: Open (leakage current: 0.1 mA max.)	ON: Supply voltage short-circuited or supply voltage within 1.5 V OFF: Open (leakage current: 0.1 mA max.)	
Functions	Measurement value display, set value/light level/resolution display, sca digit changes, sample hold, peak hold, bottom hold, peak-to-peak hol reset, ON-delay timer, OFF-delay timer, one-shot timer, deviation, pre direct threshold value setting, position teaching, 2-point teaching, aut monitor focus, (A-B) calculations*4, (A+B) calculations*4, mutual inter	vious value comparison, sensitivity adjustment, keep/clamp switch.	
Indications	Operation indicators: High (orange), pass (green), low (yellow), 7-segment main display (red), 7-segment subdisplay (yellow), laser ON (green), zero reset (green), enable (green)		
Power supply voltage	12 to 24 VDC ±10%, Ripple (p-p): 10% max.		
Current consumption	140 mA max. with power supply voltage of 24 VDC (with Sensor connected)		
Ambient temperature	Operating: 0 to 50°C, Storage: –15 to 60°C (with no icing or condensation)		
Ambient humidity	Operating and storage: 35% to 85% (with no condensation)		
Insulation resistance	20 MΩ min. at 500 VDC		
Dielectric strength	1,000 VAC, 50/60 Hz for 1 min		
Vibration resistance (destruction)	10 to 150 Hz, 0.7-mm double amplitude 80 min each in X, Y, and Z directions		
Shock resistance (destruction)	300 m/s² 3 times each in six directions (up/down, left/right, forward/backward)		
Connection method	Prewired (standard cable length: 2 m)		
Weight (packed state)	Approx. 350 g		
Materials	Case: PBT (polybutylene terephthalate), Cover: Polycabonate		
Accessories	Instruction sheet		

^{*1.} The response speed of the linear output is calculated as the measurement period × (average count setting + 1) (with fixed sensitivity). The response speed of the judgement outputs is calculated as the measurement period × (average count setting + 1) (with fixed sensitivity).
*2. The output can be switched between a current output and voltage output using a switch on the bottom of the Amplifier Unit.
*3. Setting is possible via the monitor focus function.
*4. A Calculating Unit (ZX-CAL2) is required.
Note: For operating details, refer to the operation manual (Cat. No. Z157).

■ Calculating Unit

Item	ZX-CAL2
Applicable Amplifier Units	ZX-LD11-N/41-N, ZX-EDA11/41, ZX-TDA11/41
Current consumption	12 mA max. (supplied from the Smart Sensor Amplifier Unit)
Ambient temperature	Operating: 0 to 50 $^{\circ}\text{C}$, Storage: –15 to 60 $^{\circ}\text{C}$ (with no icing or condensation)
Ambient humidity	Operating and storage: 35% to 85% (with no condensation)
Connection method	Connector
Dielectric strength	1,000 VAC, 50/60 Hz for 1 min
Insulation resistance	100 MΩ (at 500 VDC)
Vibration resistance (destructive)	10 to 150 Hz, 0.7-mm double amplitude 80 min each in X, Y, and Z directions
Shock resistance (destructive)	300 m/s² 3 times each in six directions (up/down, left/right, forward/backward)
Materials	Display: Acrylic, Case: ABS resin
Weight (packed state)	Approx. 50 g
Accessories	Instruction sheet


■ ZX-series Communications Interface Unit

	Item	ZX-SF11
Current co	nsumption	60 mA max. (supplied by the Amplifier Unit)
Applicable	Amplifier Units	ZX Series
Applicable versions	Amplifier Unit	ZX-LDA□1-N Ver. 1.000 or higher ZX-EDA□1 Ver. 1.100 or higher ZX-TDA□1 Ver. 1.000 or higher
Max. No. o	f Amplifier Units	5
Commu- nications	Communica- tions port	RS-232C port (9-pin D-Sub Connector)
functions	Communica- tions protocol	CompoWay/F*
	Baud rate	38,400 bps
	Data configura- tion	Data bits: 8, Parity: none, Start bits: 1, Stop bits: 1, Flow control: none
Indicators		Power supply: green, Sensor communications: green, Sensor communications error: red, External terminal communications: green, External terminal communications error: red
Protective	circuits	Reverse polarity protection
Ambient te	emperature	Operating: 0 to 50°C, storage: –15 to 60°C (with no icing or condensation)
Ambient h	umidity	Operating and storage: 35% to 85% (with no condensation)
Insulation resistance		20 MΩ min. (at 500 VDC)
Dielectric s	strength	1,000 VAC, 50/60 Hz for 1 min, Leakage current: 10 mA max.
Materials		Case: PBT (polybutylene terephthalate), Cover: Polycarbonate
Accessorie	es	Instruction sheet, 2 clamps


^{*} Contact your OMRON representative for CompoWay/F communications specifications.

Dimensions (Unit: mm)


■ Sensor Heads (Diffuse Reflective)




■ Sensor Heads (Regular Reflective)




■ Sensor Heads (Through-beam)






■ Amplifier Units



16

■ Accessories (Order Separately)





Ordering Information

■ Sensors

Sensor Heads

Shape	Dimensions	Sensing distance	Resolution *1	Model
Cylindrical	3 dia. x 18 mm	0.5 mm	1 μm	ZX-EDR5T
	5.4 dia. x 18 mm	1 mm		ZX-ED01T *2
	8 dia. x 22 mm	2 mm		ZX-ED02T *2
Screw-shaped	M10 x 22 mm			ZX-EM02T *2
	M18 x 46.3 mm	7 mm		ZX-EM07MT *2
Flat	30 x 14 x 4.8 mm	4 mm		ZX-EV04T *2 *3
Heat-resistant, cylindrical	M12 x 22 mm	2 mm		ZX-EM02HT *4

^{*1.} For an average count of 4096.

Amplifier Units

Appearance	Power supply	Output type	Model
	DC	NPN	ZX-EDA11
		PNP	ZX-EDA41

Note: Compatible connection with the Sensor Head.

Accessories (Order Separately)

Amplifier Mounting Brackets

Appearance	Model	Remarks
2.5	ZX-XBE1	Attached to each Sensor Head
	ZX-XBE2	For DIN track mounting

ZX-CAL2 Calculating Unit

Refer to pages 12 and 14 for details.

ZX-SF11 ZX-series Communications Interface Unit

Refer to pages 12 and 14 for details.

ZX-XC□A Cable with Connectors on Both Ends (for Extension)

Refer to page 12 for details.

ZX-SW11V3 Smart Monitor Sensor Setup Tool for Personal Computer Connection

Refer to page 12 for details.

^{*2.} Models with Protective Spiral Tubes are also available. Add a suffix of "-S" to the above model numbers when ordering. (Example: ZX-ED01-S)

^{*3.} Be sure to use ZX-EDA Amplifier Unit version 1,200 or later with the ZX-EV04T.

^{*4.} Be sure to use ZX-EDA□ Amplifier Unit version 1,300 or later with the ZX-EM02HT.

Specifications

■ Sensor Heads

		Model	ZX-EDR5T	ZX-ED01T	ZX-ED02T/ EM02T	ZX-EM07MT	ZX-EV04T	ZX-EM02HT
Measurement rang	е		0 to 0.5 mm	0 to 1 mm	0 to 2 mm	0 to 7 mm	0 to 4 mm	0 to 2 mm
Sensing object			Magnetic metals (Measurement ra	nges and lineariti	es are different f	or non-magnetic	metals.)
Standard reference	object		$18 \times 18 \times 3 \text{ mm}$		$30\times30\times3~\text{mm}$	$60 \times 60 \times 3 \text{ mm}$		$45 \times 45 \times 3 \text{ mm}$
			Material: ferrous (S50C)				
Resolution *1			1 μm					
Linearity *2			±0.5% F.S.					±1.0% F.S. *5
Linear output rang	е		Same as measure	ement range.				
Temperature characteristic *3 (including Amplifier Unit)		0.15% F.S./°C	0.07% F.S./°C				0.1% F.S./°C	
	Operatin	g *4	0 to 50°C (with no	-10 to 60°C (wit	th no icing or con	densation)		−10 to 200°C
ature	Storage	orage *4 icing or condensation) –20 to 70°C (with no icing or condensation)				–20 to 200°C		
Ambient humidity			Operating and storage: 35% to 85% (with no condensation)					
Insulation resistan	се		50 M $Ω$ min. (at 500 DC)					
Dielectric strength			1,000 VAC, 50/60 Hz for 1 min between charged parts and case					
Vibration resistance	e (desti	ruction)	10 to 55 Hz with 1.5-mm double amplitude for 2 h each in X, Y, and Z directions					
Shock resistance (destruc	tion)	500 m/s², 3 times each in X, Y, and Z directions					
Degree of protection	on (Sens	sor Head)	IEC60529, IP65	IEC60529, IP67				IEC60529, IP60 *6
Connection metho	d		Connector relay (s	standard cable le	ngth: 2 m)			
Weight (packed sta	ate)		Approx. 120 g	Approx. 140 g		Approx. 160 g	Approx. 130 g	Approx. 160 g
Materials Sensor Head Bras		Brass	Stainless steel	Brass		Zinc (nickel- plated)	Brass	
		Sensing surface					PEEK	
	Preampl	ifier	er PES					
Accessories			Amplifier Mounting	g Brackets (ZX-X	BE1), Instruction	Manual		

^{*1.} Resolution: The resolution is the deviation (±3 s) in the linear output when connected to the ZX-EDA Amplifier Unit. The above values indicate the deviations observed 30 minutes after the power is turned ON.

⁽The resolution is measured with OMRON's standard reference object at 1/2 of the measurement range with the ZX-EDA set for the maximum average count of 4096.)

The resolution is given at the repeat accuracy for a stationary workpiece, and is not an indication of the distance accuracy. The resolution may be adversely affected under strong electromagnetic fields.

^{*2.} Linearity: The linearity is given as the error in an ideal straight line displacement output when measuring the standard reference object. The linearity and measurement values vary with the object being measured.

^{*3.} Temperature characteristic: The temperature characteristic is measured with OMRON's standard reference object at 1/2 of the measurement

^{*4.} The ambient temperature given is only for the sensor head. It is -10 to 60°C for the preamp.

^{*5.} The value given is for an ambient temperature of 25°C.

^{*6.} Do not use in moist environments because the case is not waterproof.

■ Amplifier Units

Model	ZX-EDA11	ZX-EDA41			
Measurement period	150 ∝s				
Possible average count settings *1	1, 2, 4, 8, 16, 32, 64, 128, 256, 512, 1,024, 2,048, or 4,096				
Linear output *2	Current output: 4 to 20 mA/F.S., Max. load resistance: 300 Ω				
	Voltage output: ± 4 V (\pm 5 V, 1 to 5 V *3), Output imp	edance: 100 Ω			
Judgement outputs	NPN open-collector outputs, 30 VDC, 50 mA max.	PNP open-collector outputs, 30 VDC, 50 mA max.			
(3 outputs: HIGH/PASS/LOW)	Residual voltage: 1.2 V max.	Residual voltage: 2 V max.			
Zero reset input, timing input, reset input, judgement output hold input	ON: Short-circuited with 0-V terminal or 1.5 V or less	ON: Supply voltage short-circuited or supply voltage within 1.5 V			
Imput, judgement output noid input	OFF: Open (leakage current: 0.1 mA max.)	OFF: Open (leakage current: 0.1 mA max.)			
Function		/set value/output value/resolution display			
T direction	- Linearity adjustment (materials selection)	- Scaling			
	- Display reverse - Display OFF n				
	- Number of display digit changes - Sample hold	- Peak hold			
	- Bottom hold, peak-to-peak hold - Self-peak hold - Average hold - Delay hold	- Self-bottom hold - Zero reset			
	- Average noid - Delay noid - Initial reset - Linearity initial				
	- OFF-delay timer - One-shot time				
		Id value setting - Position teaching			
	- Automatic teaching - Hysteresis wid				
		tput hold input - Monitor focus			
	- Linear output correction - (A-B) calculati				
	- K-(A+B) calculation *4 - Mutual interference prevention *4				
	- Sensor disconnection detection - Zero reset memory - Zero reset indicator - Key lock				
Indications	Judgement indicators: High (orange), pass (green), low (yellow), 7-segment main digital display (red),				
	7-segment sub-digital display (yellow), power ON (green), zero reset (green), enable (green)				
Voltage influence	0.5% F.S. of linear output value at ±20% of power supply voltage				
(including Sensor)					
Power supply voltage	12 to 24 VDC ±10%, Ripple (p-p): 10% max.				
Current consumption	140 mA max. with power supply voltage of 24 VDC	,			
Ambient temperature	Operating and storage: 0 to 50°C (with no icing or co	-			
Ambient humidity	Operating and storage: 35% to 85% (with no conder	nsation)			
Insulation resistance	20 MΩ min. (at 500 DC)				
Dielectric strength	1,000 VAC, 50/60 Hz for 1 min				
Vibration resistance (destruction)	10 to 150 Hz with 0.7-mm double amplitude for 80 min each in X, Y, and Z directions				
Shock resistance (destruction)	300 m/s ² , 3 times each in 6 directions (up, down, lef	t, right, forward, backward)			
Connection method	Prewired (standard cable length: 2 m)				
Weight (packed state)	Approx. 350 g				
Materials	Case: PBT (polybutylene terephthalate), Cover: Poly	ycarbonate			
Accessories	Instruction Manual				

^{*1.} The response speed of the linear output is calculated as the measurement period · (average count setting + 1).

The response speed of the judgement outputs is calculated as the measurement period · (average count setting + 1).

Note: For operating details, refer to the operation manual (Cat. No. Z166).

^{*2.} The output can be switched between a current output and voltage output using a switch on the bottom of the Amplifier Unit.

^{*3.} A Calculating Unit (ZX-CAL2) is required. Setting is possible via the monitor focus function.

^{*4.} A Calculating Unit (ZX-CAL2) is required.


Dimensions

Sensors

Sensor Heads


ZX-EDR5T

Dimensions with Mounting Bracket Attached




ZX-ED01T

Dimensions with Mounting Bracket Attached




ZX-ED02T

Dimensions with Mounting Bracket Attached




ZX-EM02T

Dimensions with Mounting Bracket Attached




ZX-EM07MT

Dimensions with Mounting Bracket Attached




Dimensions with Mounting Declet Attacked




ZX Series (ZX-E) Smart Sensors (Inductive Displacement Type)

OMRON

ZX-EM02HT





0000

Vinyl-insulated round cable 5.1 dia., 9 conductors, standard length: 200 mm



Mounting Hole Cutout Dimensions

-15.6--

15 dia


Toothed washer



-58.2

Amplifier Units


ZX-EDA11 ZX-EDA41



Accessories (Sold Separately)

Preamplifier Mounting Brackets

ZX-XBE1



Mounting Hole Cutout Dimensions




ZX-CAL2 Calculating Unit

Refer to page 17 for details.

ZX-SF11 ZX-series CommunicationsInterface Unit

Refer to page 17 for details.

ZX-XBE2



ZX-XC1A (1 m), ZX-XC4A (4 m), ZX-XC8A (8 m) Cables with Connectors on Both Ends (for Extension)

Refer to page 17 for details.

OMRON



Ordering Information

■ Sensors

Sensor Heads

Size	Туре	Sensing distance	Resolution (See note.)	Model
6 dia.	Short type	1 mm	0.1 ∝m	ZX-TDS01T
6 dia.	Standard type	4 mm	0.1 ∝m	ZX-TDS04T
6 dia.	Low measurement type	4 mm	0.1 ∝m	ZX-TDS04T-L

Note: The resolution refers to the minimum value that can be read when a ZX-TDA 1 Amplifier Unit is connected.

■ Amplifier Units

Appearance	Power supply	Output type	Model
	DC	NPN	ZX-TDA11
		PNP	ZX-TDA41

■ Accessories (Order Separately)

Preamplifier Mounting Brackets

Appearance	Model	Remarks
	ZX-XBT1	Attached to each Sensor Head
	ZX-XBT2	For DIN track mounting

ZX-CAL2 Calculating Unit

Refer to pages 12 and 14 for details.

ZX-SF11 ZX-series Communications Interface Unit

Refer to pages 12 and 14 for details.

ZX-XC□A Cable with Connectors on Both Ends (for Extension)

Refer to page 12 for details.

ZX-SW11V3 Smart Monitor Sensor Setup Tool for Personal Computer Connection

Refer to page 12 for details.

Specifications

■ Sensor Heads

Itei	n	ZX-TDS01T	ZX-TDS04T	ZX-TDS04T-L	
Measurement rang	е	1 mm	4 mm		
Maximum actuator	travel distance	Approx. 1.5 mm	Approx. 5 mm		
Resolution *1		0.1 ∝m			
Linearity *2		0.3% F.S.			
Operating force *3		Approx. 0.7 N		Approx. 0.25 N	
Degree of protection	on (Sensor Head)	IEC60529, IP67		IEC60529, IP54	
Mechanical durabi	lity	10,000,000 operations min.			
Ambient temperature		Operating: 0°C to 50°C (with no icing or condensation) Storage: -15°C to 60°C (with no icing or condensation)			
Ambient humidity		Operating and storage: 35% to 85% (with no icing or condensation)			
Temperature Sensor Head		0.03% F.S./°C			
characteristic *4	Preamplifier	0.01% F.S./°C			
Vibration resistant (destruction)	e	10 to 55 Hz with 0.35-mm single amplitude in the X, Y, and Z directions			
Shock resistance (destruction)		150 m/s², 3 times each in the X, Y, and Z directions			
Connection metho	d	Connector relay (standard cable length: 2 m)			
Isolation		Isolated (Sensor Head enclosure and I/O lines)			
Weight (packed state)		Approx. 100 g			
Materials Sensor Head Rubber boot Preamplifier		Stainless steel			
		Fluorocarbon rubber Silicon rubber			
		Polycarbonate			
Accessories		Instruction manual, Preamplifier Mounting Brackets (ZX-XBT1)			

^{*1.} The resolution is given as the minimum value that can be read when a ZX-TDA□1 Amplifier Unit is connected. This value is taken 15 minutes after turning ON the power with the average number of operations set to 256.

^{*2.} The linearity is given as the error in an ideal straight line displacement output.

^{*3.} These figures are representative values that apply for the measurement mid-point, and are for when the provided actuator is used, with the actuator moving downwards. If the actuator moves horizontally or upwards, the operating force will be reduced. Also, if an actuator other than the standard one is used, the operating force will vary with the weight of the actuator itself.

^{*4.} These figures are representative values that apply for the mid-point of the measurement range.

■ Amplifier Units

Item	ZX-TDA11 ZX-TDA41				
Measurement period	1 ms				
Possible average count settings *1	1, 2, 4, 8, 16, 32, 64, 128, 256, 512, or 1,024				
Linear output *2	Current output: 4 to 20 mA/F.S., Max. load resist Voltage output: ± 4 V (± 5 V, 1 to 5 V), Output im				
Judgement outputs (3 outputs: HIGH/PASS/LOW)	NPN open-collector outputs, 30 VDC, 30 mA marketidual voltage: 1.2 V max.	ax.	PNP open-collector outputs, 30 VDC, 30 mA max. Residual voltage: 2 V max.		
Zero reset input, timing input, reset input, judgement output hold input	ON: Short-circuited with 0-V terminal or 1.5 V or OFF: Open (leakage current: 0.1 mA max.)	r less	ON: Supply voltage short-circuited or supply voltage of 1.5 V or less OFF: Open (leakage current: 0.1 mA max.)		
Function	- Measurement value display - Display reverse - Sample hold - Self-peak hold - Self-peak hold - Self-peak hold - Initial reset - Hysteresis width setting - Judgement output hold input - (A+B) calculations *4 - Zero reset memory - Clamp value setting - Span adjustment - Warming-up display		- Number of display digit changes - Bottom hold, peak-to-peak hold - Zero reset setting - Position teaching - Reset input - (A-B) calculations '4		
Indicators	Judgement indicators: High (orange), pass (green), low (yellow), 7-segment main digital display (red), 7-segment sub-digital display (yellow), power ON (green), zero reset (green), enable (green)				
Power supply voltage	12 to 24 VDC ±10%, Ripple (p-p): 10% max.	12 to 24 VDC ±10%, Ripple (p-p): 10% max.			
Current consumption	140 mA max. (with Sensor connected), For 24-VDC power supply: 140 mA max. (with Sensor connected)				
Ambient temperature	Operating and storage: 0 to 50°C (with no icing	or condensation)			
Ambient humidity	Operating and storage: 35% to 85% (with no ici	ng or condensation)			
Temperature characteristic	0.03% F.S./°C				
Insulation resistance	20 M Ω min. at 500 VDC				
Dielectric strength	1,000 VAC, 50/60 Hz for 1 min				
Vibration resistance (destruction)	10 to 150 Hz with 0.7-mm double amplitude for 80 min each in X, Y, and Z directions				
Shock resistance (destruction)	300 m/s², 3 times each in six directions (up, down, left, right, forward, backward)				
Connection method	Prewired (standard cable length: 2 m)				
Weight (packed state)	Арргох. 350 g				
Materials	Case: PBT (polybutylene terephthalate), Cover:	: Polycarbonate			
Accessories	Instruction sheet				

^{*1.} The response speed of the linear output is calculated as the measurement period · (average count setting + 1).

The response speed of the judgement outputs is calculated as the measurement period · (average count setting + 1).


Note: For operating details, refer to the operation manual (Cat. No. E346) provided by OMRON.

Options (Actuators)

M	odel	Type (material)	Screw section Appearance		Application	Applicable Sensor *
						ZX-TDS□T
D5SN-	TB1	Ball type (steel)	Female screw M2.5 x 0.45		Measuring ordinary flat surfaces (standard actuator supplied with the ZX-TDS Series)	\circ
	TB2	Ball type (carbide steel)	Female screw M2.5 x 0.45		Measurements where abrasion resistance is critical Measured objects: Carbide (HR90) or lower.	\circ
	ТВ3	Ball type (ruby)	Female screw M2.5 x 0.45		Measurements where abrasion resistance is critical Measured objects: Carbide (HR90) or higher.	0
	TN1	Needle type (carbide steel)	Male screw M2.5 x 0.45		Measuring the bottom of grooves and holes	\triangle
	TF1	Flat (carbide steel)	Male screw M2.5 x 0.45		Measuring spherical objects	\triangle
	ТА	Conversion Adapter (stainless steel)	Through-hole fe- male screw M2.5 x 0.45		Mounting D5SN-TN1/-TF1 or commercially available actuators on ZX-TDS-series Sensors	0

Note: For optional Actuator combinations, the circle means the Actuator is replaceable and the triangle means that a Conversion Adapter is required.

■ Dimensions



32 **ZX Series (ZX-T)** Smart Sensors (High-precision Contact Type)

^{*2.} The output can be switched between a current output and voltage output using a switch on the bottom of the Amplifier Unit.


^{*3.} Setting is possible via the monitor focus function.

^{*4.} A Calculating Unit (ZX-CAL2) is required.


Dimensions

Sensors

ZX-TDS01T




ZX-TDS04T ZX-TDS04T-L



Amplifier Units


ZX-TDA11 ZX-TDA41



■ Accessories (Order Separately)

Preamplifier Mounting Bracket (Supplied with Each Sensor)


ZX-XBT1



Mounting Hole Cutout Dimensions



ZX-XBT2 (For DIN Track Mounting)



ZXCAL2 Calculating Unit

Refer to page 17 for details.

ZX-SF11 ZX-series CommunicationsInterface Unit

Refer to page 17 for details.

ZX-XC1A (1 m), ZX-XC4A (4 m), ZX-XC8A (8 m) Cables with Connectors on Both Ends (for Extension)

Refer to page 17 for details.

Precautions

■ Design Precautions

Conform to the specified ratings and performance. Refer to the *Specifications* for each product on the following pages.

ZX-L: Pages 13 and 14 ZX-E: Pages 21 and 22 ZX-T: Pages 31 and 32

Environment

Do not operate the product in locations subject to flammable or explosive gases.

In order to ensure safe operation and maintenance, do not install the product in the vicinity of high-voltage devices or power equipment.

■ Correct Use

This product consists of precision parts that may fail if it is dropped.

<u>Design Precautions</u> Compatibility

Sensors and Amplifier Units are mutually compatible. Sensors can be added or replaced individually.

Influence of High-frequency Electromagnetic Fields

Using the product in the vicinity of devices that generate high-frequency electromagnetic fields, such as ultrasonic cleaning equipment, high-frequency generators, transceivers, mobile phones, and inverters, may result in malfunction.

Wiring

Wiring Check

After wiring is completed, before turning ON the power, confirm that the power supply is connected correctly, that there are no faulty connections, such as load short-circuits, and that the load current is correct. Incorrect wiring may result in failure.

Cable Extension

Do not extend the cable for the Sensor and the Amplifier Unit to a length exceeding 10 m. Use a ZX-XC□A Extension Cable (sold separately) to extend the Sensor's cable. Extend the Amplifier Unit's cable using a shielded cable of the same type.

Wiring

Do not use the product at voltages exceeding the rated values. Doing so may result in damage.

Do not connect the product to an AC power supply or connect the power supply in reverse.

Do not short loads connected to open-collector outputs.

Do not lay the cable for the product together with or in the same duet as high-voltage lines or power lines. Doing so may result in incorrect operation or damage due to induction.

Other Precautions

Do not attempt to disassemble, repair, or modify the product.

Dispose of the product using standard procedures for industrial waste.

Do not connect combinations of ZX-L□□-, ZX-E□□-, and ZX-T□□-series Smart Sensors.

Power Supply

When using a commercially available switching regulator, ground the FG (frame ground) terminal.

If the power supply line is subject to surges, connect a surge absorber that meets the conditions of the operating environment.

Calculating Unit

When using a Calculating Unit, connect the linear output ground of the corresponding Amplifier Unit.

Connectors

Do not connect or disconnect connectors while the power is ON.

Be sure hold to connectors by the cover when connecting or disconnecting.

Installation Location

Do not install the product in the following locations.

- Locations subject to temperatures outside the specified range
- Locations subject to condensation due to sudden temperature changes
- Locations subject to humidity levels outside range 35% to 85%
- · Locations subject to corrosive or flammable gases
- · Locations subject to dust, salts, or metallic powder.
- Locations directly subject to vibrations and shocks
- · Locations subject to splashes of water, oil, or chemicals
- · Locations subject to strong electromagnetic or electrical fields

Maintenance and Inspection

- Be sure to turn OFF the power supply before adjusting or removing the Sensor Head.
- · Cleaning:

Do not use thinners, benzine, acetone, or kerosene for cleaning.

Terms and Conditions of Sale

- Offer; Acceptance. These terms and conditions (these "Terms") are deemed part of all quotes, agreements, purchase orders, acknowledgments, price lists, catalogs, manuals, brochures and other documents, whether electronic or in writing, relating to the sale of products or services (collectively, the "<u>Products</u>") by Omron Electronics LLC and its subsidiary companies ("<u>Omron</u>"). Omron objects to any terms or conditions proposed in Buyer's purchase order or other documents which are inconsistent with, or in addition to, these Terms
- Prices: Payment Terms. All prices stated are current, subject to change without notice by Omron. Omron reserves the right to increase or decrease prices on any unshipped portions of outstanding orders. Payments for Products are due net 30 days unless otherwise stated in the invoice.
- Discounts. Cash discounts, if any, will apply only on the net amount of invoices sent to Buyer after deducting transportation charges, taxes and duties, and will be allowed only if (i) the invoice is paid according to Omron's payment terms
- and (ii) Buyer has no past due amounts.

 Interest. Omron, at its option, may charge Buyer 1-1/2% interest per month or the maximum legal rate, whichever is less, on any balance not paid within the stated terms
- Orders. Omron will accept no order less than \$200 net billing.
- Governmental Approvals. Buyer shall be responsible for, and shall bear all costs involved in, obtaining any government approvals required for the importation or sale of the Products.
- Taxes. All taxes, duties and other governmental charges (other than general real property and income taxes), including any interest or penalties thereon, imposed directly or indirectly on Omron or required to be collected directly or indirectly by Omron for the manufacture, production, sale, delivery, importation, consumption or use of the Products sold hereunder (including customs duties and sales, excise, use, turnover and license taxes) shall be charged to and remitted by Buyer to Omron.
- Financial. If the financial position of Buyer at any time becomes unsatisfactory to Omron, Omron reserves the right to stop shipments or require satisfactory security or payment in advance. If Buyer fails to make payment or otherwise comply with these Terms or any related agreement. Omron may (without liability and in addition to other remedies) cancel any unshipped portion of Products sold hereunder and stop any Products in transit until Buyer pays all amounts, including amounts payable hereunder, whether or not then due, which are owing to it by Buyer. Buyer shall in any event remain liable for all
- Cancellation: Etc. Orders are not subject to rescheduling or cancellation unless Buyer indemnifies Omron against all related costs or expenses.
- 10. Force Majeure. Omron shall not be liable for any delay or failure in delivery resulting from causes beyond its control, including earthquakes, fires, floods, strikes or other labor disputes, shortage of labor or materials, accidents to machinery, acts of sabotage, riots, delay in or lack of transportation or the requirements of any government authority.
- Shipping: Delivery. Unless otherwise expressly agreed in writing by Omron:
 Shipments shall be by a carrier selected by Omron; Omron will not drop ship except in "break down" situations.
 - b. Such carrier shall act as the agent of Buyer and delivery to such carrier shall constitute delivery to Buyer; c. All sales and shipments of Products shall be FOB shipping point (unless other
 - erwise stated in writing by Omron), at which point title and risk of loss shall pass from Omron to Buyer; provided that Omron shall retain a security interest in the Products until the full purchase price is paid; d. Delivery and shipping dates are estimates only; and e. Omron will package Products as it deems proper for protection against nor-
- mal handling and extra charges apply to special conditions.

 12. Claims. Any claim by Buyer against Omron for shortage or damage to the Products occurring before delivery to the carrier must be presented in writing to Omron within 30 days of receipt of shipment and include the original transportation bill signed by the carrier noting that the carrier received the Products from Omron in this condition claims. from Omron in the condition claimed.
- Warranties. (a) Exclusive Warranty. Omron's exclusive warranty is that the Products will be free from defects in materials and workmanship for a period of twelve months from the date of sale by Omron (or such other period expressed in writing by Omron). Omron disclaims all other warranties, express or implied.

 (b) <u>Limitations</u>. OMRON MAKES NO WARRANTY OR REPRESENTATION, EXPRESS OR IMPLIED, ABOUT NON-INFRINGEMENT, MERCHANTABIL-

- ITY OR FITNESS FOR A PARTICULAR PURPOSE OF THE PRODUCTS. BUYER ACKNOWLEDGES THAT IT ALONE HAS DETERMINED THAT THE PRODUCTS WILL SUITABLY MEET THE REQUIREMENTS OF THEIR INTENDED USE. Omron further disclaims all warranties and responsibility of INI ENDED USE. Office further disclaims all warranties and responsibility of any type for claims or expenses based on infringement by the Products or otherwise of any intellectual property right. (c) <u>Buyer Remedy</u>. Omron's sole obligation hereunder shall be, at Omron's election, to (i) replace (in the form originally shipped with Buyer responsible for labor charges for removal or replacement thereof) the non-complying Product, (ii) repair the non-complying Product, or (iii) repay or credit Buyer an amount equal to the purchase price of the non-complying Product; provided that in no event shall Omron be responsible for warranty repair indemnity or any other claims or expresse readding. ble for warranty, repair, indemnity or any other claims or expenses regarding the Products unless Omron's analysis confirms that the Products were properly handled, stored, installed and maintained and not subject to contamination, abuse, misuse or inappropriate modification. Return of any Products by Buyer must be approved in writing by Omron before shipment. Omron Companies shall not be liable for the suitability or unsuitability or the results from the use of Products in combination with any electrical or electronic components, circuits, system assemblies or any other materials or substances or environments. Any advice, recommendations or information given orally or in writing, are not to be construed as an amendment or addition to the above warranty See http://oeweb.omron.com or contact your Omron representative for published information.
- lished information.

 Limitation on Liability: Etc. OMRON COMPANIES SHALL NOT BE LIABLE FOR SPECIAL, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES, LOSS OF PROFITS OR PRODUCTION OR COMMERCIAL LOSS IN ANY WAY CONNECTED WITH THE PRODUCTS, WHETHER SUCH CLAIM IS BASED IN CONTRACT, WARRANTY, NEGLIGENCE OR STRICT LIABILITY. Further, in no event shall liability of Omron Companies exceed the individual price of the Product on which liability is asserted.

 Indemnities. Buyer shall indemnify and hold harmless Omron Companies and their employees from and against all liabilities, losses, claims, costs and expenses (including attorneys fees and expenses) related to any claim inves-
- expenses (including attorney's fees and expenses) related to any claim, investigation, litigation or proceeding (whether or not Omron is a party) which arises or is alleged to arise from Buyer's acts or omissions under these Terms or in any way with respect to the Products. Without limiting the foregoing, Buyer (at its own expense) shall indemnify and hold harmless Omron and defend or settle any action brought against such Companies to the extent based on a claim that any Product made to Buyer specifications infringed intellectual property
- that any Product made to buyer specifications immiged interlectual property rights of another party.

 Property: Confidentiality. Any intellectual property in the Products is the exclusive property of Omron Companies and Buyer shall not attempt to duplicate in any way without the written permission of Omron. Notwithstanding any charges to Buyer for engineering or tooling, all engineering and tooling shall remain the exclusive property of Omron. All information and materials supplied. by Omron to Buyer relating to the Products are confidential and proprietary, and Buyer shall limit distribution thereof to its trusted employees and strictly
- prevent disclosure to any third party.

 <u>Export Controls.</u> Buyer shall comply with all applicable laws, regulations and licenses regarding (i) export of products or information; (iii) sale of products to "forbidden" or other proscribed persons; and (ii) disclosure to non-citizens of regulated technology or information.

 Miscellaneous. (a) Waiver. No failure or delay by Omron in exercising any right
- Miscellaneous. (a) Waiver. No failure or delay by Omron in exercising any right and no course of dealing between Buyer and Omron shall operate as a waiver of rights by Omron. (b) Assignment. Buyer may not assign its rights hereunder without Omron's written consent. (c) Law. These Terms are governed by the law of the jurisdiction of the home office of the Omron company from which Buyer is purchasing the Products (without regard to conflict of law principles). (d) Amendment. These Terms constitute the entire agreement between Buyer and Omron relating to the Products, and no provision may be changed or waived unless in writing signed by the parties. (e) Severability. If any provision hereof is rendered ineffective or invalid, such provision shall not invalidate any other provision. (f) Setoff. Buyer shall have no right to set off any amounts against the amount owing in respect of this invoice. (g) Definitions. As used herein, "including" means "including without limitation"; and "Omron Companies" (or similar words) mean Omron Corporation and any direct or indirect subsidiary or affiliate thereof. subsidiary or affiliate thereof.

Certain Precautions on Specifications and Use

- <u>Suitability of Use.</u> Omron Companies shall not be responsible for conformity with any standards, codes or regulations which apply to the combination of the Product in the Buyer's application or use of the Product. At Buyer's request, Omron will provide applicable third party certification documents identifying ratings and limitations of use which apply to the Product. This information by itself is not sufficient for a complete determination of the suitability of the Product in combination with the end product, machine, system, or other application or use. Buyer shall be solely responsible for determining appropriateness of the particular Product with respect to Buyer's application, product or system. Buyer shall take application responsibility in all cases but the following is a non-exhaustive list of applications for which particular attention must be given: Outdoor use, uses involving potential chemical contamination or electrical interference, or conditions or uses not described in this document.

 - (ii) Use in consumer products or any use in significant quantities.
 (iii) Energy control systems, combustion systems, railroad systems, aviation systems, medical equipment, amusement machines, vehicles, safety equipment, and installations subject to separate industry or government regulations. (iv) Systems, machines and equipment that could present a risk to life or property. Please know and observe all prohibitions of use applicable to this Prod-
 - NEVER USE THE PRODUCT FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY OR IN LARGE QUANTITIES WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO

- ADDRESS THE RISKS, AND THAT THE OMRON'S PRODUCT IS PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.
- OVERALL EQUIPMENT OR SYSTEM.

 Programmable Products. Omron Companies shall not be responsible for the user's programming of a programmable Product, or any consequence thereof.

 Performance Data. Data presented in Omron Company websites, catalogs and other materials is provided as a guide for the user in determining suitability and does not constitute a warranty. It may represent the result of Omron's test conditions, and the user must correlate it to actual application requirements. Actual performance is subject to the Omron's Warranty and Limitations of Liability.
- Change in Specifications. Product specifications and accessories may be changed at any time based on improvements and other reasons. It is our practice to change part numbers when published ratings or features are changed, or when significant construction changes are made. However, some specifications of the Product may be changed without any notice. When in doubt, special part numbers may be assigned to fix or establish key specifications for your application. Please consult with your Omron's representative at any time
- to confirm actual specifications of purchased Product.

 <u>Errors and Omissions.</u> Information presented by Omron Companies has been checked and is believed to be accurate; however, no responsibility is assumed for clerical, typographical or proofreading errors or omissions.



Complete "Terms and Conditions of Sale" for product purchase and use are on Omron's website at www.omron.com/oei – under the "About Us" tab, in the Legal Matters section.

ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

 $To \ convert \ millimeters \ into \ inches, \ multiply \ by \ 0.03937. \ To \ convert \ grams \ into \ ounces, \ multiply \ by \ 0.03527.$

OMRON ELECTRONICS LLC

One Commerce Drive Schaumburg, IL 60173

847-843-7900

For US technical support or other inquiries:

OMRON CANADA, INC. 885 Milner Avenue

Toronto, Ontario M1B 5V8

416-286-6465

OMRON ON-LINE

Global - http://www.omron.com USA - http://www.omron.com/oei Canada - http://www.omron.ca

800-556-6766

Cat. No. E351-E1-02

8/06

Specifications subject to change without notice

Printed in USA